Under Review Notification

Raised By: Vanessa Morel Product #: RBE350A93-3307-00

Date: 2019.10.23 Product Name: TAIL GEARBOX SEAL EXTRACTOR

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBE350A93-3307-00	RBE350A93-3307-00 Rev 2A	Υ	Υ	N	Υ	Υ	N	N	Ν	19-933	See below

Description of Issue:

Issues stated on ADR (Manufacturing issues)

RBE350A93-3307-00 and items -01 and -03 must be put on **HOLD** in Plex

RBE350A93-3307-00 Finish good in stock can be use as is

Items -01 and -03 must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene